



AS 332 SUPER PUMA REVISION STATUS

REVISED: 08-10-2017

TYPE OF AIRCRAFT: AS332C - L - L1

<u>MANUAL</u>	<u>REVISION</u>	<u>DATED</u>	<u>RUSH</u>	<u>DATED</u>
DESCRIPTION & OPERATION MANUAL (DOM) CUSTOMIZED	1	02-06-17		Info on ORION
MASTER SERVICING MANUAL				
C CHAPTER 4	4	02-06-17		
C CHAPTER 5	4	02-06-17		
L CHAPTER 4	4	02-06-17		
L CHAPTER 5	4	02-06-17		
L1-L1e CHAPTER 4	4	02-06-17		
L1-L1e CHAPTER 5	4	02-06-17		
MAINTENANCE MANUAL (MWC)	1	02-06-17		
CUSTOMIZED (Applicable for County of LA only)	0	10-15-15		
REPAIR MANUAL- STRUCTURAL (MRM)	1	02-06-17		
REPAIR MANUAL - TRANSMISSION (MRS)	1	02-06-17		
STORAGE PRESERVATION MANUAL (SPM)	1	02-06-17		
ILLUSTRATED PARTS CATALOG (IPC)	1	02-06-17		
TOOL CATALOG (T/C)	0	02-06-17		
FAULT ISOLATION (FIM)	1	02-06-17		
WIRING DIAGRAM MANUAL (WDM) TYPE 1	0	04-07-16		
WIRING DIAGRAM MANUAL (WDM) TYPE 2	0	10-15-15		
SERVICE BULLETINS	SEE INDEXES			
SERVICE LETTERS	SEE INDEXES			
MOD INDEX	3	02-06-17		
ORION LIGHT USB	1	04-10-17		
COMPONENT MAINTENANCE MANUAL USB	25	06-13-16		
<b>STANDARD PRACTICES MANUAL</b>	<b>6</b>	<b>06-19-17</b>		
SERVICE LETTER CD-ROM	ISSUE 5	01-01-10		
FLIGHT MANUAL "C" FAA	SEE F/M REVISION STATUS			
FLIGHT MANUAL "L" FAA	SEE F/M REVISION STATUS			
FLIGHT MANUAL "L1" FAA	SEE F/M REVISION STATUS			

\*\*FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2017  
AS332 SUPER PUMA

REVISED: 10-17-2017

AIRFRAME SERVICE BULLETINS

AIRFRAME SERVICE BULLETINS

SAFETY INFORMATION NOTICES

<u>S/B</u>	<u>DATED</u>	<u>S/B</u>	<u>DATE</u>	<u>I/N</u>	<u>DATE</u>
EASB 01.00.86	17-30			2546-I-24 RN1	12-19-16
EASB 01.00.86 RN1	17-34			2832-I-00	06-07-17
EASB 05.01.07 RN6	17-30			2832-I-00 RN1	06-26-17
05.00.92 RN2	17-20			2934-I-26 RN1	05-23-17
EASB 05.01.17 RN3	17-08			2934-I-26 RN2	08/08/17
EASB 05.01.07 RN4	17-11			3087-I-13 RN1	06-22-17
EASB 05.01.07 RN5	17-28			3094-I-63	01-11-17
24.00.58	17-15			3095-S-63	3-17-17
25.03.11 RN1	16-46			3095-S-63 RN1	03-24-17
25.03.11 ERR	16-46			3095-S-63 RN2	06-06-17
25.03.37	17-12			3099-I-22	01-12-17
25.03.52	17-23			3101-I-24	12-19-16
28.00.64 RN3 ERR	16-42			3107-I-67	01-13-17
29.00.17 RN1	17-08			3117-I-71 RN1	03-08-17
29.00.19 RN1	17-20			3121-I-63	03-17-17
30.00.84	17-13			3121-I-63 RN1	03-24-17
<b>34.00.36 RN1</b>	<b>17-40</b>			3121-I-63 RN2	06-06-17
34.00.56	17-17			3125-I-64	07-07-17
40.00.48	17-15			3134-I-00	03-01-17
52.00.24 RN4	17-17			3134-I-00 RN1	03-23-17
52.00.48	17-11			3136-S-71	04-05-17
52.00.48 ERR	17-11			3136-S-71 RN1	04-10-17
EASB 52.00.49 RN2	17-35			3137-I-53	04-10-17
ASB 52.00.52	17-35			3138-I-31	05-22-17
ASB 52.00.52 ERR	17-35			3140-I-00	07-25-17
ASB 52.00.56	17-05			3142-S-00	06-06-17
52.00.57	17-38			3149-S-11	05-03-17
53.01.76 RN4	16-51			<b>3153-I-33</b>	<b>10-02-17</b>
53.01.88 RN1	16-51			3160-I-67	06-07-17
53.01.92 RN0	16-51			3162-I-00	08-11-17
53.01.94	16-51			3166-I-67	06-15-17
53.01.94 RN1	17-31			3167-I-00	06-07-17
53.01.99	17-11			3170-S-00	06-26-17
53.02.01	17-17			<b>3170-S-00 RN1</b>	<b>10-03-17</b>
53.02.02	17-19			3173-S-63	06-23-17
56.00.09 RN1	16-49			3173-S-63 RN1	08-17-17
63.00.69 RN4	17-20			<b>3180-I-00</b>	<b>07-31-17</b>
ASB 63.00.74 RN1	17-28			3181-I-63 RN1	08-07-17
EASB 63.00.83 RN2	17-25			3181-I-63 RN2	08-28-17
63.00.84	17-30			3181-I-63 RN3	09-22-17
				3183-I-00	08-28-17
				3184-S-62	08-03-17