



AS 355 TWINSTAR REVISION STATUS

REVISED: 08-09-2017  
 AIRCRAFT: AS355E-F-F1-F2-N-NP

<u>MANUAL</u>	<u>CODE</u>	<u>REVISION</u>	<u>REV DATE</u>	<u>RUSH REV</u>	<u>REV DATE</u>
DESCRIPTION & OPERATION MANUAL	MDF	3	09-19-16		
MASTER SERVICING MANUAL	MSR				
F CHAP 4		6	09-19-16		
F CHAP 5		6	09-19-16		
F1 CHAP 4		6	09-19-16		
F1 CHAP 5		6	09-19-16		
F2 CHAP 4		7	09-19-16		
F2 CHAP 5		6	09-19-16		
N CHAP 4		6	09-19-16		
N CHAP 5		6	09-19-16		
NP CHAP 4		6	09-19-16		
NP CHAP 5		6	09-19-16		
MAINTENANCE MANUAL	MET	3	09-19-16		
STRUCTURAL REPAIR MANUAL	MRS	3	09-19-16		
REPAIR MANUAL - TRANSMISSION SYSTEM	MRM	3	09-19-16		
STORAGE MANUAL	MST	3	09-19-16		
ILLUSTRATED PARTS CATALOG E-F-F1-F2-N	IPC	1	09-19-16		
ILLUSTRATED PARTS CATALOG NP	IPC	1	09-19-16		
TOOL CATALOG (except NP)	ICO	1	09-19-16		
TOOL CATALOG NP VERSION	ICO	1	09-19-16		
FAULT ISOLATION MANUAL	MFI	3	09-19-16		
WIRING DIAGRAMS MANUAL	MCS	3	09-19-16		
INDEX OF MODICATIONS	SIM	3	09-09-16		
<b>STANDARD PRACTICES MANUAL</b>	<b>MTC</b>	<b>6</b>	<b>06-19-17</b>		
FLIGHT MANUAL "ALL VERSIONS"	PMV	SEE SEPARATE SRD			
SERVICE BULLETINS	SBT	SEE INDEXES			
INFORMATION NOTICES	IN	SEE INDEXES			
O.R.I.O.N. LIGHT USB KEY	ORIL	3	11-07-2016		
COMPONENT MAINTENANCE MANUAL USB	ECMM	26	03-23-17		
INFORMATION NOTICE CD-ROM		8	01-01-15		

\*\*FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

**SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2017**  
**355 TWINSTAR**

**REVISED: 10-17-17**

**AIRFRAME SERVICE BULLETINS**

**SAFETY INFORMATION NOTICE**

<u>S/B</u>	<u>DATED</u>	<u>I/N</u>	<u>DATE</u>
ASB 05.00.59 RN2	17-04	2832-I-00	06-07-17
05.00.70 RN1	16-50	2832-I-00 RN1	06-26-17
EASB 05.00.75	17-04	2934-I-26 RN1	05-23-17
EASB 05.00.75 RN1	17-06	2934-I-26 RN2	08-08-17
05.00.76	17-22	3042-I-67 RN1	01-11-17
EASB 05.00.76	17-26	3054-S-64 ERR	12-19-16
ASB 05.00.77	17-27	3060-I-79	01-23-17
23.00.06 RN1	17-05	3095-S-63	03-17-17
34.00.19	17-07	3095-S-63 RN1	03-24-17
52.00.24 RN1	17-32	3095-S-63 RN2	06-06-17
55.00.03 RN3	17-07	3127-I-62	04-13-17
55.00.10	17-12	3134-I-00	03-01-17
60.00.02 RN3	17-05	3134-I-00 RN1	03-23-17
ASB 62.00.35	17-07	3142-S-00	06-06-17
EASB 62.00.36	17-20	3144-I-80	04-13-17
EASB 62.00.36 RN1	17-20	<b>3153-I-33</b>	<b>10-02-17</b>
63.00.25 RN2	17-25	3162-I-00	08-11-17
65.00.17 ERR RN3	16-45	3167-I-00	06-07-17
65.00.19 ERR RN2	16-45	3170-S-00	06-26-17
64.00.07 RN2	17-39	<b>3170-S-00 RN1</b>	<b>10-03-17</b>
64.00.08	17-39	<b>3180-I-00</b>	<b>07-31-17</b>
ASB 67.00.42 RN2	17-04	3183-I-00	08-28-17
ASB 67.00.42 RN3	17-36		
71.00.03 RN2	17-06		
80.00.10 RN1	17-04		