



AS 332 SUPER PUMA REVISION STATUS

REVISED: 11-06-2017

TYPE OF AIRCRAFT: AS332C - L - L1

| <u>MANUAL</u>                                 | <u>REVISION</u>         | <u>DATED</u>  | <u>RUSH</u> | <u>DATED</u> |
|---|-------------------------|---------------|-------------|--------------|
| DESCRIPTION & OPERATION MANUAL (DOM)          | 1                       | 02-06-17      |             |              |
| CUSTOMIZED                                    |                         | Info on ORION |             |              |
| <b>MASTER SERVICING MANUAL</b>                |                         |               |             |              |
| C CHAPTER 4                                   | 5                       | 07-10-17      |             |              |
| C CHAPTER 5                                   | 5                       | 07-10-17      |             |              |
| L CHAPTER 4                                   | 5                       | 07-10-17      |             |              |
| L CHAPTER 5                                   | 5                       | 07-10-17      |             |              |
| L1-L1e CHAPTER 4                              | 5                       | 07-10-17      |             |              |
| L1-L1e CHAPTER 5                              | 5                       | 07-10-17      |             |              |
| <b>MAINTENANCE MANUAL (MWC)</b>               |                         |               |             |              |
| CUSTOMIZED (Applicable for County of LA only) | 2                       | 07-10-17      |             |              |
|   | 0                       | 10-15-15      |             |              |
| <b>REPAIR MANUAL- TRANSMISSION (MRM)</b>      |                         |               |             |              |
| REPAIR MANUAL - STRUCTURAL (MRS)              | 2                       | 07-10-17      |             |              |
|   | 1                       | 02-06-17      |             |              |
| <b>STORAGE PRESERVATION MANUAL (SPM)</b>      |                         |               |             |              |
|   | 2                       | 07-10-17      |             |              |
| <b>ILLUSTRATED PARTS CATALOG (IPC)</b>        |                         |               |             |              |
|   | 2                       | 07-10-17      |             |              |
| <b>TOOL CATALOG (T/C)</b>                     |                         |               |             |              |
|   | 1                       | 07-10-17      |             |              |
| <b>FAULT ISOLATION (FIM)</b>                  |                         |               |             |              |
|   | 1                       | 02-06-17      |             |              |
| <b>WIRING DIAGRAM MANUAL (WDM) TYPE 1</b>     |                         |               |             |              |
|   | 0                       | 04-07-16      |             |              |
| <b>WIRING DIAGRAM MANUAL (WDM) TYPE 2</b>     |                         |               |             |              |
|   | 0                       | 10-15-15      |             |              |
| <b>SERVICE BULLETINS</b>                      |                         |               |             |              |
|   | SEE INDEXES             |               |             |              |
| <b>SERVICE LETTERS</b>                        |                         |               |             |              |
|   | SEE INDEXES             |               |             |              |
| <b>MOD INDEX</b>                              |                         |               |             |              |
|   | 4                       | 07-10-17      |             |              |
| <b>ORION LIGHT USB</b>                        |                         |               |             |              |
|   | 2                       | 10-16-17      |             |              |
| <b>COMPONENT MAINTENANCE MANUAL USB</b>       |                         |               |             |              |
|   | 25                      | 06-13-16      |             |              |
| <b>STANDARD PRACTICES MANUAL</b>              |                         |               |             |              |
|   | 6                       | 06-19-17      |             |              |
| <b>SERVICE LETTER CD-ROM</b>                  |                         |               |             |              |
|   | ISSUE 5                 | 01-01-10      |             |              |
| <b>FLIGHT MANUAL "C" FAA</b>                  |                         |               |             |              |
|   | SEE F/M REVISION STATUS |               |             |              |
| <b>FLIGHT MANUAL "L" FAA</b>                  |                         |               |             |              |
|   | SEE F/M REVISION STATUS |               |             |              |
| <b>FLIGHT MANUAL "L1" FAA</b>                 |                         |               |             |              |
|   | SEE F/M REVISION STATUS |               |             |              |

\*\*FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2017  
AS332 SUPER PUMA

REVISED: 10-27-2017

| <u>AIRFRAME SERVICE BULLETINS</u> |              | <u>AIRFRAME SERVICE BULLETINS</u> |             | <u>SAFETY INFORMATION NOTICES</u> |             |
|-----------------------------------|--------------|-----------------------------------|-------------|-----------------------------------|-------------|
| <u>S/B</u>                        | <u>DATED</u> | <u>S/B</u>                        | <u>DATE</u> | <u>I/N</u>                        | <u>DATE</u> |
| EASB 01.00.86                     | 17-30        |                                   |             | 2546-I-24 RN1                     | 12-19-16    |
| EASB 01.00.86 RN1                 | 17-34        |                                   |             | 2832-I-00                         | 06-07-17    |
| EASB 05.01.07 RN6                 | 17-30        |                                   |             | 2832-I-00 RN1                     | 06-26-17    |
| 05.00.92 RN2                      | 17-20        |                                   |             | 2934-I-26 RN1                     | 05-23-17    |
| EASB 05.01.17 RN3                 | 17-08        |                                   |             | 2934-I-26 RN2                     | 08/08/17    |
| EASB 05.01.07 RN4                 | 17-11        |                                   |             | 3087-I-13 RN1                     | 06-22-17    |
| EASB 05.01.07 RN5                 | 17-28        |                                   |             | 3094-I-63                         | 01-11-17    |
| 24.00.58                          | 17-15        |                                   |             | 3095-S-63                         | 3-17-17     |
| 25.03.11 RN1                      | 16-46        |                                   |             | 3095-S-63 RN1                     | 03-24-17    |
| 25.03.11 ERR                      | 16-46        |                                   |             | 3095-S-63 RN2                     | 06-06-17    |
| 25.03.37                          | 17-12        |                                   |             | 3099-I-22                         | 01-12-17    |
| 25.03.52                          | 17-23        |                                   |             | 3101-I-24                         | 12-19-16    |
| <b>26.00.09 RN2</b>               | <b>17-40</b> |                                   |             | 3107-I-67                         | 01-13-17    |
| 28.00.64 RN3 ERR                  | 16-42        |                                   |             | 3117-I-71 RN1                     | 03-08-17    |
| 29.00.17 RN1                      | 17-08        |                                   |             | 3121-I-63                         | 03-17-17    |
| 29.00.19 RN1                      | 17-20        |                                   |             | 3121-I-63 RN1                     | 03-24-17    |
| 30.00.84                          | 17-13        |                                   |             | 3121-I-63 RN2                     | 06-06-17    |
| 34.00.36 RN1                      | 17-40        |                                   |             | 3125-I-64                         | 07-07-17    |
| 34.00.56                          | 17-17        |                                   |             | 3134-I-00                         | 03-01-17    |
| 40.00.48                          | 17-15        |                                   |             | 3134-I-00 RN1                     | 03-23-17    |
| 52.00.24 RN4                      | 17-17        |                                   |             | 3136-S-71                         | 04-05-17    |
| 52.00.48                          | 17-11        |                                   |             | 3136-S-71 RN1                     | 04-10-17    |
| 52.00.48 ERR                      | 17-11        |                                   |             | 3137-I-53                         | 04-10-17    |
| EASB 52.00.49 RN2                 | 17-35        |                                   |             | 3138-I-31                         | 05-22-17    |
| ASB 52.00.52                      | 17-35        |                                   |             | 3140-I-00                         | 07-25-17    |
| ASB 52.00.52 ERR                  | 17-35        |                                   |             | 3142-S-00                         | 06-06-17    |
| ASB 52.00.56                      | 17-05        |                                   |             | 3149-S-11                         | 05-03-17    |
| 52.00.57                          | 17-38        |                                   |             | 3153-I-33                         | 10-02-17    |
| 53.01.76 RN4                      | 16-51        |                                   |             | 3160-I-67                         | 06-07-17    |
| 53.01.88 RN1                      | 16-51        |                                   |             | 3162-I-00                         | 08-11-17    |
| 53.01.92 RN0                      | 16-51        |                                   |             | 3166-I-67                         | 06-15-17    |
| 53.01.94                          | 16-51        |                                   |             | 3167-I-00                         | 06-07-17    |
| 53.01.94 RN1                      | 17-31        |                                   |             | 3170-S-00                         | 06-26-17    |
| 53.01.99                          | 17-11        |                                   |             | 3170-S-00 RN1                     | 10-03-17    |
| 53.02.01                          | 17-17        |                                   |             | 3173-S-63                         | 06-23-17    |
| 53.02.02                          | 17-19        |                                   |             | 3173-S-63 RN1                     | 08-17-17    |
| 56.00.09 RN1                      | 16-49        |                                   |             | 3180-I-00                         | 07-31-17    |
| 63.00.69 RN4                      | 17-20        |                                   |             | 3181-I-63 RN1                     | 08-07-17    |
| ASB 63.00.74 RN1                  | 17-28        |                                   |             | 3181-I-63 RN2                     | 08-28-17    |
| EASB 63.00.83 RN2                 | 17-25        |                                   |             | 3181-I-63 RN3                     | 09-22-17    |
| 63.00.84                          | 17-30        |                                   |             | 3183-I-00                         | 08-28-17    |
|                                   |              |                                   |             | 3184-S-62                         | 08-03-17    |